



Item: EL502 – Men’s Lithium Quilted Hooded Jacket

PRODUCT MEASUREMENTS

	S	M	L	XL	2XL	3XL	Tolerance
Body Length <i>measure from neck (CB)</i>	28	29	30	30 ¾	31 ½	32 ¼	½ +/-
Chest Width <i>1 inch below armhole</i>	22 ½	23 ½	24 ½	26 ½	28 ½	30 ½	½ +/-
Across Shoulder	16 ½	17	18	19	20	21	¼ +/-
Bottom Opening Width <i>Straight</i>	21 ½	22 ½	23 ½	25 ½	27 ½	29 1/2	½ +/-
Sleeve Length (CB)	35 ½	36 ½	37 ½	38 ¼	39	39 ¾	½ +/-

ALL MEASUREMENTS IN INCHES

CB
Center Back

CHEST 1 INCH DOWN
Measure the front of the garment 1 inch down from the armhole

1/2
Measure only the front of the garment, then double that measurement to get the total circumference

RELAXED
Do not stretch the garment if it has elastic to measure, simply leave the elastic relaxed

STRETCHED
Stretch the garment if it has elastic to measure, measure stretched